




Extent of realized geological works:

- geophysical measurements - 700 m
- exploratory non-equipped boreholes (Geoprobe probes) - 23 pcs
- equipped monitoring boreholes - 7 pcs
- hydrodynamic tests - 2 pcs
- sampling work and field measurements
- laboratory work
- drawing up a final report with a risk analysis
- drawing up a feasibility study of remediation



Customer:



Ministry of Environment of the Slovak Republic
Námestie Ľ. Štúra 1
812 35 Bratislava

Contractor of geological works:

Group
of suppliers
- EB SURVEY



EKOHYDROGEO
ŽITNÝ



Geological Survey Results:

- contamination of the mineral environment by non-polar extractables C10-C40 was found, also Cr and Ni, mainly in the contact zone
- ground water pollution by 1,1,2,2-tetrachloroethene, has been proven, locally also by non-polar extractables and C10-C40
- the presence of environmental risk from pollution of the mineral environment in the contact zone, or from the spread of groundwater pollution has not been proven in the territory
- the presence of health risks has not been demonstrated



Budget of geological task: **93 705 €** (excluding VAT)

Solution time: **5/2015 - 10/2015**



ENVIGEO, Inc. Kynceľová 2, 974 11 Banská Bystrica

tel: **+421 (48) - 471 24 30**

fax: **+421 (48) - 471 24 23**

mail: **envigeo@envigeo.sk**

web: **www.envigeo.eu**